PROPOSAL NO.
 *
 INVITATION FOR BID
 *
 DATE
 *
 PAGE

 *
 SCHEDULE A
 *
 *
 *
 *
 *
 1 of 7

 BM-09
 *
 EARNED PREMIUM &
 *
 April 14, 2004
 *
 1 of 7

 LOSS EXPERIENCE INFO

SCHEDULE A

THIS SCHEDULE DOES NOT NEED TO BE RETURNED.

EARNED PREMIUM AND LOSS EXPERIENCE INFORMATION

This schedule contains earned premium and loss experience information for the past five (5) years.

I. HISTORICAL INFORMATION

POLICY PERIOD	AGENT OF RECORD	COMPANY
07-01-1998/2001	AON Risk Services	Hartford Steam Boiler Inspection &
07-01-2001/2004	Risk Services of Louisiana	Insurance Company

	NET	POLICY LIMITS			ORM
POLICY PERIOD	PREMIUM	BUSINESS INCOME	OTHER	RETENTION	
07-01-1998/1999	344,114	278,103,400	15,000,000	Liability	\$50,000
07-01-1999/2000	356,556	241,923,821	5,000,000	Extra Expense	Combined Single Limit
07-01-2000/2001	380,169	239,861,434	250,000	Water Damage	Per Accident
07-01-2001/2002	542,778	272,369,232	250,000	Ammonia Contamination	
07-01-2002/2003	591,473	271,580,438	250,000	Hazardous Substance	
07-01-2003/12-31-2003*	613,047	272,433,000	250,000	Consequential Damage	
			250,000	Expediting Expense	

II. LOSS EXPERIENCE (As of 1-7-2004)

POLICY PERIOD	NUMBER OF LOSSES INCURRED	TOTAL LOSSES INCURRED BY ORM	TOTAL LOSSES INCURRED BY EXCESS CARRIER	LARGEST SINGLE LOSS
07-01-1998/1999	106	1,010,978	433,364	396,614
07-01-1999/2000	85	857,444	218,112	188,274
07-01-2000/2001	76	583,934	37,261	68,121
07-01-2001/2002	57	770,030	-0-	49,000
07-01-2002/2003	77	1,090,059	344,945	315,000
07-01-2003/12-31-2004*	19	306,567	-0-	49,000

^{*} as of 1/7/04

PROPOSAL NO.	*	INVITATION FOR BID	*	DATE	*	PAGE
	*	SCHEDULE A	*		*	
BM-09	*	EARNED PREMIUM &	*	April 14, 2004	*	2 of 7
		LOSS EXPERIENCE INFO				
THIS SCHEDULE DOES NOT NEED TO BE RETURNED.						

III. DETAIL LOSS EXPERIENCE

The following reports reflect detail information for losses over \$10,000.

07-01-1998/1999 as of February 3, 2004

ACC.DATE COV DESC OF LOSS - KEY 3 101/25/99 510 3068-090 CARRIER #2 CHILLER HAS WATER IN SYSTEM 19407.00 19407.00 19407.00 103/04/99 510 UNDERGROUND IS.8 KVA CABLE GROUNDED TO DNR & ED 22129.00 .00 12407.00 103/14/99 510 UNDERGROUND IS.8 KVA CABLE GROUNDED TO DNR & ED 22129.00 .00 12407.00 103/14/99 510 UNDERGROUND STATE AND A CABLE GROUNDED TO DNR & ED 22129.00 .00 107/13.60 .00 107/13.60 .00 107/13.60 .00 107/13.60 .00 107/13.60 .00				
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$	ACC.DATE COV DESC OF LOSS - KEY 3	TOTAL-PAID	CLM.RECOV	NET-CLAIM
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$	01/25/99 510 30GB-090 CARRIER #2 CHILLER HAS WATER IN SYSTEM	19407.00	.00	19407.00
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$	03/04/99 510 UNDERGROUND 13.8 KVA CABLE GROUNDED TO DNR & ED	22129.00	.00	22129.00
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$		13755.06	.00	13755.06
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$		17713.60	. 00	
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$		42450.00	. 00	
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$	04/09/99 510 60-TON TRANE CHILLER BARREL RUPTURED & REACH	32875.50	.00	
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$		44450 00	inn	
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$	06/26/00 BIO LICUTATING CAUSED SINGLE PHASING TO A/C & DEEP	11100.00	.00	
05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 333072.02 333072.02 49000.00 P 05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED; 382072.02 333072.02 49000.00 T 06/07/99 510 4160 VOLTS TO 208/120 500 KVA TXFM FAILED AT 27175.26 .00 27175.26 06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/03/98 510 132 KVA UNDERGROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 116879.76 .00 2654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 2 MED 49000.00 83481.92 .08 \$	05/11/00 E10 13 SYVA TYEM WITH 1EVV INTERPRETED COMMIND 9	13566 60	.00	
06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/24/98 510 132 KV4 UNDERGROUND CABLE GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED & GEOLOGY & PSYCH- 27025.87 .00 27025.87 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 540256.43 .00 40256.43 T08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD & MED 49000.00 83481.92 .08 \$	US/11/77 SIG 13.2KVM TAPH WITH ISKV INTERROFTER GROUNDED &	10340.00	.00	
06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/24/98 510 132 KV4 UNDERGROUND CABLE GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED & GEOLOGY & PSYCH- 27025.87 .00 27025.87 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 540256.43 .00 40256.43 T08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD & MED 49000.00 83481.92 .08 \$	05/31/99 510 ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED;	49000.00	.00	49000.00 P
06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/24/98 510 132 KV4 UNDERGROUND CABLE GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED & GEOLOGY & PSYCH- 27025.87 .00 27025.87 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 540256.43 .00 40256.43 T08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD & MED 49000.00 83481.92 .08 \$	05/31/99 51F ALLISON GAS FIRED TURBINE FOR CHILLER #6 FAILED;	333072.02	333072.02	.00 S
06/15/99 510 SUPERIOR SCOTCH MARINE BOILER SPLIT FIRE TUBE; 18391.00 .00 18391.00 07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT 40442.20 .00 40442.20 07/24/98 510 132 KV4 UNDERGROUND CABLE GROUNDED WHEN CONTRACT 10780.26 .00 10780.26 08/20/98 510 0;13.8KV-3PHASE TXFM GROUNDED & GEOLOGY & PSYCH- 27025.87 .00 27025.87 08/27/98 510 UNDERGROUND FEEDER FAULTED 108/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 540256.43 .00 40256.43 T08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD & MED 49000.00 83481.92 .08 \$		382072.02	333072.02	49000.00 T
08/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 S 40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD a MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S		27175.26	.00	E1113.E0
08/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 S 40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD a MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S		18391.00	.00	
08/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 S 40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD a MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S	07/03/98 510 3-2037; COOLING TOWER MOTOR GROUNDED AT LAFAYETT	40442.20	.00	40442.20
08/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 S 40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD a MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S	07/24/98 510 132 KVÁ UNDERGROUND CABLE GROUNDED WHEN CONTRACT	10780.26	.00	10780.26
08/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 S 40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD a MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S		27025.87	.00	
08/28/98 510 FIRE TUBE RUPTRD IN 85,000 LB BOILER 28654.00 .00 28654.00 P 08/28/98 520 ZURN WATER SUPERHEATER TUBE RUPTURED 11602.43 .00 11602.43 S 40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD a MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S		16879.76	.00	16879.76
40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 0 MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S	08/28/98 510 FIRE TUBE RUPTRD IN 85.000 LB BOTLER	28654.00	.00	28654.00 P
40256.43 .00 40256.43 T 08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD 0 MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 S	08/28/98 520 ZURN WATER SUPERHEATER TURE RUPTURED	11602.43	.00	
08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD @ MED 49000.00 .00 49000.00 P 08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN 83482.00 83481.92 .08 \$	OU EU / OU EU	40256 43	.00	
				40250140 1
	08/29/98 520 1000-TON YRK CENTRIFICAL,500 UNIT, SCRMBLD @ MED	49000.00	.00	49000.00 P
	08/29/98 51F 1000-TON YORK #2 CHILLER BROKEN	83482.00	83481.92	.08 S
09/03/98 510 UNDERGROUND CABLE FAULTED WHEN TXFM SHORTED & 4058.56 09/03/98 510 17.5 KW EMPIRE GENRATR GROUNDED 12026.36 .00 12026.36 10/14/98 510 LEGISLATIVE ELEVATOR DAMAGED 16164.45 .00 16164.45 11/09/98 510 SUPERIOR PIERLESS CAST IRON BOILER LEAKED AT STU 23365.00 .00 23365.00 11/15/98 510 4-WIRE UNDERGROUND CABLE FAULTED BETWEEN MAIN 10758.79 .00 10758.79 11/16/98 510 CHILLER BARREL BURST ON CARRIER 30G0455312 ADMIN 23514.00 .00 23514.00 11/28/98 510 #5 SUPERHEATER TUBE IN ZURN BOILER #5 RUPTURED 15936.30 .00 15936.30 12/01/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 22024.30 .00 22024.30 12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT 2 SVM 32209.00 .00 32209.00				49000.08 T
09/03/98 510 17.5 KW EMPTRE GENRATR GROUNDED 12026.36 .00 12026.36 10/14/98 510 LEGISLATIVE ELEVATOR DAMAGED 16164.45 .00 16164.45 11/09/98 510 SUPERIOR PIERLESS CAST IRON BOILER LEAKED AT STU 23365.00 .00 23365.00 11/15/98 510 4-WIRE UNDERGROUND CABLE FAULTED BETWEEN MAIN 10758.79 .00 10758.79 11/16/98 510 CHILLER BARREL BURST ON CARRIER 30G045531a ADMIN 23514.00 .00 23514.00 11/28/98 510 #5 SUPERHEATER TUBE IN ZURN BOILER #5 RUPTURED 15936.30 .00 15936.30 12/01/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 22024.30 .00 22024.30 12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT a SVM 32202.00 .00 32209.00	09/03/98 510 UNDERGROUND CABLE FAULTED WHEN TXFM SHORTED &	44058.56	.00	44058.56
10/14/98 510 LEGISLATIVE ELEVATOR DAMAGED 11/109/98 510 SUPERIOR PIERLESS CAST IRON BOILER LEAKED AT STU 11/109/98 510 SUPERIOR PIERLESS CAST IRON BOILER LEAKED AT STU 11/15/98 510 4-WIRE UNDERGROUND CABLE FAULTED BETWEEN MAIN 11/16/98 510 CHILLER BARREL BURST ON CARRIER 30G0455313 ADMIN 11/16/98 510 CHILLER BARREL BURST ON CARRIER 30G0455313 ADMIN 11/16/98 510 WES SUPERHEATER TUBE IN ZURN BOILER #5 RUPTURED 11/16/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 12/101/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 12/101/98 510 SQUARE D, 750KVA TXFM FAULTED 12/201/98 510 \$48 AIR HANDLER HUB DISLODGED & BROKE UNIT 3 SVM 32209.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT 3 SVM 32209.00 10 32209.00	09/03/98 510 17.5 KW EMPIRE GENRATR GROUNDED	12026.36	.00	12026.36
11/09/98 510 SUPERIOR PIERLESS CAST IRON BOILER LEAKED AT STU 23365.00 .00 23365.00 11/15/98 510 4-WIRE UNDERGROUND CABLE FAULTED BETWEEN MAIN 10758.79 .00 10758.79 11/16/98 510 CHILLER BARREL BURST ON CARRIER 30806455312 ADMIN 23514.00 .00 .00 23514.00 11/28/98 510 #5 SUPERHEATER TUBE IN ZURN BOILER #5 RUPTURED 15936.30 .00 15936.30 12/01/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 22024.30 .00 22024.30 12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT 2 SVM 32209.00 .00 32209.00	10/14/98 510 LEGISLATIVE ELEVATOR DAMAGED	16164.45	.00	16164.45
11/15/98 510 4-WIRE UNDERGROUND CABLE FAULTED BETWEEN MAIN 10758.79 .00 10758.79 11/16/98 510 CHILLER BARREL BURST ON CARRIER 30G045531a ADMIN 23514.00 .00 23514.00 11/28/98 510 #5 SUPERHEATER TUBE IN ZURN BOILER #5 RUPTURED 15936.30 .00 15936.30 12/01/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 22024.30 .00 22024.30 12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT a SVM 32209.00 .00 32209.00	11/09/98 510 SUPERIOR PIERLESS CAST IRON BOILER LEAKED AT STU	23365.00	.00	23365.00
11/16/98 510 CHILLER BARREL BURST ON CARRIER 30G0455313 ADMIN 23514.00 .00 23514.00 11/28/98 510 #5 SUPERHEATER TUBE IN ZURN BOILER #5 RUPTURED 15936.30 .00 15936.30 12/01/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 22024.30 .00 22024.30 12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT 3 SVM 32209.00 .00 32209.00	11/15/98 510 4-WIRE UNDERGROUND CABLE FAULTED BETWEEN MAIN	10758.79	. 0 0	10758.79
11/28/98 510 #5 SUPERHEATER TUBE IN ZURN BOILER #5 RUPTURED 15936.30 .00 15936.30 12/01/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 22024.30 .00 22024.30 12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT & SVM 32209.00 .00 32209.00	11/16/98 510 CHILLER BARREL BURST ON CARRIER 30G0455319 ADMIN	23514.00	.00	23514.00
12/01/98 510 350 HP VARIABLE SPEED DRIVE MOTOR SINGLE PHASED 22024.30 .00 22024.30 12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT a SVM 32209.00 .00 32209.00		15936.30	.00	
12/04/98 510 SQUARE D, 750KVA TXFM FAULTED 29664.00 .00 29664.00 12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT a SVM 32209.00 .00 32209.00		22024.30	.00	
12/28/98 510 #8 ATR HANDLER HUB DISLODGED & BROKE UNIT a SVM 32209.00 .00 32209.00	12/06/98 510 SQUARE D. 750KVA TYEM FAULTED	29664.00	.00	29664.00
10/00/00 PIO LIGHTHING OTHERS APPARE LINES AND THE PARE TO THE TOTAL TOT	12/28/98 510 #8 AIR HANDLER HUB DISLODGED & BROKE UNIT a SVM	32209.00	.00	32209.00
12/28/98 510 L1GHINING SIRUCK AERIAL LINES-SURGE DMG 112.5KVA 36625.35 .UU 36625.35	12/28/98 510 LIGHTNING STRUCK AERIAL LINES-SURGE DMG 112.5KVA	36625.35	.00	36625.35

07-01-1999/2000 as of February 3, 2004

ACC.DATE COV DESC OF LOSS - KEY 3 01/10/00 510 TRANSFER SWITCH 3 21 REX ST. SUBSTATION GROUNDED 02/13/00 510 BOTH MCQUAY 50-TON COMPRESSORS & OTHER EQUIP.DMG 02/17/00 510 GEARBOX FAILURE TO CERAMIC COOLING TOWER FAN 03/15/00 510 MAIN 13.8 KVA SWITCHGEAR GROUNDED***********************************
02/13/00 510 BOTH MCQUAY 50-TON COMPRESSORS & OTHER EQUIP.DMG 25326.32 .00 14410.30 .00 14410.30 .00 2717/00 510 GEARBOX FAILURE TO CERAMIC COOLING TOWER FAN 25326.32 .00 253
03/15/00 510 MAIN 13.8 KVA SWITCHGEAR GROUNDED***********************************
03/15/00 510 MAIN 13.8 KVA SWITCHGEAR GROUNDED***********************************
03/15/00 51F MAIN 13.8 KVA SWITHGEAR GROUNDED 61371.50 61
03/15/00 51F MAIN 13.8 KVA SWITHGEAR GROUNDED 61371.50 61
04/10/00 510 13.5 KVA OIL FILLED TXFM GROUNDED AT OLD SCIENCE 27219.85 .00 27219.85 P 04/10/00 520 13.5 KVA OIL TXFM GROUNDED & OLD SCIENCE BLDG 4000.00 .00 4000.00 S 31219.85 .00 31219.85 T 04/12/00 510 800-TON DUNHAM BUSH SCREW COMPRESSOR OIL PUMP 25948.75 .00 25948.75 04/19/00 510 UNDERGROUND ELECTRIC CABLES GROUND FAULTED & GAS 10950.00 .00 10950.00 04/26/00 510 50-TON COPELAND MODEL & DPI 5000 (MCQUAY) 10553.00 .00 10553.00 05/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED & DSOB 325 45450.14 .00 45450.14 05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
04/10/00 520 13.5 KVA OIL TXFM GROUNDED a OLD SCIENCE BLDG 4000.00 .00 4000.00 S 31219.85 T 04/12/00 510 800-TON DUNHAM BUSH SCREW COMPRESSOR OIL PUMP 25948.75 .00 25948.75 04/19/00 510 UNDERGROUND ELECTRIC CABLES GROUND FAULTED a GAS 10950.00 .00 10950.00 04/26/00 510 50-TON COPELAND MODEL 8 DPI 5000 (MCQUAY) 10553.00 .00 10553.00 05/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED 3050 325 45450.14 .00 45450.14 05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
04/10/00 520 13.5 KVA OIL TXFM GROUNDED a OLD SCIENCE BLDG 4000.00 .00 4000.00 S 31219.85 T 04/12/00 510 800-TON DUNHAM BUSH SCREW COMPRESSOR OIL PUMP 25948.75 .00 25948.75 04/19/00 510 UNDERGROUND ELECTRIC CABLES GROUND FAULTED a GAS 10950.00 .00 10950.00 04/26/00 510 50-TON COPELAND MODEL 8 DPI 5000 (MCQUAY) 10553.00 .00 10553.00 05/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED 3050 325 45450.14 .00 45450.14 05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
04/12/00 510 800-TON DUNHAM BUSH SCREW COMPRESSOR OIL PUMP 31219.85 T 04/12/00 510 800-TON DUNHAM BUSH SCREW COMPRESSOR OIL PUMP 25948.75 .00 25948.75 04/19/00 510 UNDERGROUND ELECTRIC CABLES GROUND FAULTED a GAS 10950.00 .00 10950.00 04/26/00 510 50-TON COPELAND MODEL 8 DPI 5000 (MCQUAY) 10553.00 .00 10553.00 05/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED asoB 325 45450.14 .00 45450.14 05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
04/12/00 510 800-TON DUNHAM BUSH SCREW COMPRESSOR OIL PUMP 25948.75 .00 25948.75 .00 04/19/00 510 UNDERGROUND ELECTRIC CABLES GROUND FAULTED 8 GAS 10950.00 .00 10950.00 04/26/00 510 50-TON COPELAND MODEL 8 DPI 5000 (MCQUAD) 10553.00 .00 10553.00 .00 105/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED 80B 325 45450.14 .00 45450.14 05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
04/19/00 510 UNDERGROUND ELECTRIC CABLES GROUND FAULTED 0 GAS 10950.00 .00 10950.00 04/26/00 510 50-TON COPELAND MODEL 8 DPI 5000 (MCQUAY) 10553.00 .00 10553.00 05/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED 080B 325 45450.14 .00 45450.14 05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
04/26/00 510 50-TON COPELAND MODEL 8 DPI 5000 CMCQUAY 10553.00 .00 10553.00 .00 05/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED 808 325 45450.14 .00 45450.14 .00 45450.14 .00 45450.14 .00 13344,83
05/23/00 510 TRANE 800 TON CENTRIFICAL GROUNDED 3SOB 325 45450.14 .00 45450.14 05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
05/24/00 510 EXPANSION VALVE FAILED DAMAGING YORK COMPRESSOR 13344.83 .00 13344.83
05/24/00 510 CONDESOR ON 60 TON TRANE RUPTURED & DMG COMPRESS 43148.88 .00 43148.88
05/24/00 510 UNDERGROUND CABLE FROM LIBRARY TO FRASCH HALL 13170.60 .00 13170.60
06/14/00 510 HIGH VOLTAGE SWITCHGEAR & BUSS GROUNDED AT 39086.75 .00 39086.75
06/17/00 510 UNDERGROUND FEEDER CABLES FAULTED DURING STORM 26254.79 .00 26254.79
06/19/00 510 150-TON CARRIER CENTRIFIG2F RESTART W/O OIL DMG
06/19/00 51F 150 TON CARRIER CENTIFIGAL RAN W/O 01L 8266.99 12978.00 4711.01-S
57266.99 12978.00 44288.99 T
07/30/99 510 75-TON TRANE RECIPROCATING COMPRESSOR-2E5R68 22071.77 .00 22071.77
08/02/99 510 BREAKER FOR CHILLER #1 FAILED 21310.17 .00 21310.17
08/16/99 510 30-TON TRANE COMPRESSOR GROUNDED @ AQUA CENTER 12060.71 .00 12060.71
08/20/99 510 225KVA/13200/480 PAD MOUNTED TXFM SINGLED PHASED 10025.08 .00 10025.08
08/23/99 510 HIGH VOLTAGE BUSHING GROUNDED IN TXFM a SUB- 10174.69 .00 10174.69
08/24/99 520 2.5 MEGWATT TURBINE LOCKED UP ON RESTART 20816.00 .00 20816.00
09/09/99 510 #2-250 TON MCQUAY CHILLER DAMAGED SHAFT 45713.00 .00 45713.00
09/30/99 510 50 TON TRANE COMPRESSOR GROUNDED 10219.79 .00 10219.79 11/02/99 510 SINGLE PHASING DAMAGED TWO CHILLER CONTROLS 12108.47 .00 12108.47
11/02/99 510 CUMMINS DIESEL GENERATOR THREW ROD WHEN IT OVER- 20561.00 .00 20561.00
11/12/99 510 40,000 CFM AIRHANDLER SHAFT BROKE @ S.O.B. 11074.57 .00 11074.57

07-01-2000/2001 as of February 3, 2004

ACC.DATE COV DESC OF LOSS - KEY 3 01/16/01 510 CLEVER BROOKS BOILER DOWN/POSSIBLE SPLIT TUBES. 01/27/01 510 750 KVA TXFM GROUNDED a JOHN L. GUIDRY STADIUM	TOTAL-PAID CLM.R 22517.00 49000.00	.00 .00	NET-CLAIM 22517.00 49000.00
02/14/01 510 UTICA BOILER RUPTURED TUBE & SUGAR HALL 02/16/01 510 CUMMING GENERATOR CONTACTORS DAMAGED BY ARCING 03/09/01 510 CONDENSOR TUBES FROZE AND LEAKED REFRIGERANT 03/16/01 510 EMERGENCY GENERATORS FAILED 05/09/01 510 TXFM GROUNDED & DUNN HALL BASEMENT 06/05/01 510 TRAILER FREEZER FAILED & WAKEFIELD/MEAT SPOILED 06/06/01 510 UNDERGROUND CABLES FAULTED IN TROPICAL STORM 06/17/01 510 2-CARRIER COMP SINGLE-PHASED & INFIRM & KITCHEN 07/31/00 510 85 TON TRANE RECIPROCATING COMPRESSOR THRE ROD/ 08/02/00 510 UNDER GROUND CABLE FAULT & TAP BOX NEAR WATKINS 09/01/00 510 100-TON TRANE CG100B GROUNDED OUT & MCCOLLOUGH 09/29/00 510 TRANE 1280-TON CENTRIFUGAL GROUNDED 1200 H.P. 10/13/00 510 #1 FRICK RWB 1,500-TON CHILLER REFLECTS BEARINGS	30577.00 17357.93 14600.00 49000.00 10636.77 11047.00 14035.58 16342.00 15205.00 10777.27 15627.35 15587.90	.00 .00 .00 .00 .00 .00 .00 .00 .00	30577.00 17357.93 14600.00 49000.00 10636.77 11047.00 14035.58 16342.00 15205.00 10777.27 15627.35 15587.90
11/13/00 510 1-50-TON CARRIER & WATSON LIBRARY GROUNDED 11/20/00 510 1500 KVA SQ D PAD TXFM GROUNDED & DORM #2	3102.29 37434.98	.00 .00	49000.00 37434.98

07-01-2001/2002 as of February 3, 2004

ACC DATE COV	DEGG OF LOCAL KEY T	TOTAL DATE OF 11 OF		
ALC. DATE COV	DESC OF LUSS - KEY S	TOTAL-PAID CLM.RE		NET-CLAIM
01/17/02 510	KEWANEE, MODELL3W 300G SPLIT TUBES	.00	.00	49000.00
02/26/02 510	DESC OF LOSS - KEY 3 KEWANEE, MODELL3W 300G SPLIT TUBES 2-15-TON TRANE COMPRESSORS SINGLED PHASED a	10216.92	.00	10216.92
03/06/02 510	CITY OF RUSTON SUBSTATION FAULTED-SINGLE PHASE	23139.42	.00	23139.42
03/15/02 510	YORK 400-TON SCREW CHILLER INBOARD ROTOR FAILED	16460.25	.00	16461.00
	ALL 3-CARRIER CHILL PACS NEED REPAIRS BERG GOT			22507.50
04/18/02 510	FEEDER FOR #63A & ASTER ST. SUB-STATION FAULTED	.00	.00	20000.00
04/29/02 510	FEEDER FOR #63A @ ASTER ST. SUB-STATION FAULTED SINGLE PHASE CAUSED DAMAGE TO EQUIP	10426 35	. 00	10426.35
	85-TON TRANE THREW A ROD & LAUNDY MECHANICAL POD	16115.05	.00	16115.05
	OPEN DRIVE TRANE COMPRESSOR THREW ROD & SCHOOL		.00	13157.07
	30-TON TRANE COMPRESSOR GROUNDED a DOVER CENTER		.00	20200.00
	30-TON TRANE COMPRESSOR AND CONTACTS DMG BY SIN-			
06/02/02 510	30-100 TRANE COMPRESSOR AND CONTACTS DMG BY SIN-	11635.33	.00	11635.33
06/10/05 210	YURK A/C COMPRESSOR AND CONTROLS GROUND FAUTER	11548.00	.00	11548.00
06/24/02 510	UNDERGROUND ELECTRICAL CABLES GROUNDED	.00	.00	49000.00
06/25/02 510	U/G FEEDER FAULTED CAUSING 2-MOTORS TO SINGLE	29236.95	.00	29236.95
06/28/02 510	FLOAT SWITCH STUCK CAUSING OVERFLOW	17712.41	.00	17712.41
07/16/01 510	YORK A/C COMPRESSOR AND CONTROLS GROUND FAUTER UNDERGROUND ELECTRICAL CABLES GROUNDED U/G FEEDER FAULTED CAUSING 2-MOTORS TO SINGLE FLOAT SWITCH STUCK CAUSING OVERFLOW SINGLE PHASING DAMAGED NUMEROUS A/C MOTORS ETC.	15156.95	.00	15156.95
07/18/01 510	260-TON TRANE CHILLER/GROUNDED MOTOR	24947.00	.00	24947.00
07/23/01 510	260-TON TRANE CHILLER/GROUNDED MOTOR YORK COMPRESSOR SINGLED PHASED	17801.39	.00	17801.39
07/26/01 510	TREE LIMB FELL AND CAUSED SINGLE PHASING/NUMFR-	18872.44	.00	18872.44
07/27/01 510	GEARBOX ON CERAMIC COOLING TOWER FAILED AT	10130.00	.00	10130.00
	65-TON RECIPRICAL CARRIER GROUNDED-VIBRATION AL-		.00	17040.00
	2400 VOLT TXFM GROUNDED a NW CORNER MUSEUM OF		.00	22680.00
	YORK YCAJ44HE8-41PA (CHILLER #1) GROUNDED a ATLE	17095.45	.00	17095.45
	100 TON TRANE SINGLED PHASED & 1440 HWY90 BRIDGE	32474.75	.00	32474.75
00/21/01 510	#1 TRANE CHILLER GROUNDED AT HARVEY STATE OFFICE			
		19764.00	.00	19764.00
10/02/01 510	2-CHILLER AND 20+ PUMPS DMG WHEN SAND ENTERED	26090.59	.00	26090.59

Fiscal Year 2002/2003 as of February 3, 2004

ACC.DATE COV DESC OF LOSS - KEY 3	TOTAL-PAID	CLM.RECOV	NET-CLAIM
01/02/03 510 MAIN HIGH VOLTAGE SWITCHGEAR FIRE	49000.00	.00	49000.00 P
01/02/03 51F 13.8 KVA SWITCHGEAR ARCHED AND FAULTED/ ATS ALSO	117.18	117.18	.00 S
03/31/03 510 BOILER TUBE SPLIT AND ELECTRICAL DISTRIBUTION	49117.18	117.18	49000.00 T
	.00	.00	49000.00
04/07/03 510 POWER SPIKE CAUSED INSULATOR TO FAIL ON 4160	49000.00	.00	49000.00 P
04/07/03 51F INSULATOR AT SUBSTATION FAILED DURING TRW/4160	40000.00	40000.00	.00 S
04/25/03 510 ATC ON EMERGENCY GENERATOR FAILED AND GROUND FAU 04/30/03 510 ELECTRICAL BUSS TO FELTON CLARK FIELD FAULTED	89000.00 36270.00 .00	40000.00 .00 .00	49000.00 T 36270.00 25000.00
05/01/03 510 CLEAVER BROOKS MODEL STEAM BOILER OVERFIRING &	23962.83	.00	23962.83
05/02/03 510 225- TON TRANE CENTRIGUAL LOST OIL PRESSUE 05/02/03 51F 225 TON TRANE CENTRIFUGAL LOW SPEED SHAFT DAMAGE	25775.99	.00	25775.99 P
	.00	.00	.00 S
	25775.99	.00	25775.99 T
05/05/03 510 15KVA TXFM FAULTED AT HEALTH & PHYSICA ED BLDG	8730.51	.00	49000.00 P
05/05/03 51F 13.2 KVA TXFM FAULTED	.00		20000.00 S
05/13/03 510 HIGH VOLTAGE SWITCH #30 FAULTED / GE SWITCHGEAR 05/13/03 510 770-TON TRANE GROUNDED	8730.51	.00	69000.00 T
	.00	.00	49000.00
	19752.00	.00	19752.00
05/28/03 510 SQUIRREL IN CAPACITOR BANK CAUSED SINGLE PHASING	.00	.00	35000.00
06/09/03 510 WEST AHU POWER WHEEL ASSEMBLE BROKE AT PLEASANT	40673.37	.00	40673.37
06/17/03 510 CENTRAL PLANT TOWER #1 GEARBOX TRANSMISSION SEIZ	14979.37	.00	14979.37
06/23/03 510 POWER SPIKE DAMAGED 3 MCQUAY COMPRESSORS 07/07/02 510 LIGHTNING DAMAGED ENERGY MANAGEMENT SYSTEM 07/12/02 510 COOLING TOWER FAN BACK-DRAFTED CAUSING 2-SHAFTS	18663.12 34775.64	.00 .00	18663.12 34775.64
07/16/02 510 POWER SURGE CAUSED 3-800 TRANE COMPRESSORS TO 07/29/02 510 22 Y/O PAD MOUNTED TRANSFORMER FAILED AT PINE	12792.43	.00	12792.43
	13606.39	.00	13606.39
	23290.55	.00	23290.55
09/17/02 510 400-TON TRANE CENTRIFUGAL GROUNDED a COLISEUM-	23217.00	.00	23217.00
09/20/02 510 DUAL COIL WESTINGHOUSE TXFM BURNED ON TRANE CVHE 09/20/02 51F MAIN CHILLER FAILED REQUIRING RENTAL AIR	43229.00	.00	43229.00 P
	.00	.00	.00 S
	43229.00	.00	43229.00 T
10/03/02 510 CRACKED MANIFOLD ON #1 CUMMINS GENERATOR ALLOWED 10/03/02 510 HURRICANE LILLIE CAUSE POWER SURGES CHILLER AND	14553.16 28650.00	.00	14553.16 28650.00
10/03/02 510 KOHLER GENERATOR GROUNDED OUT DURRING HURICANE	14916.32	.00	14916.32
10/06/02 510 FAILURE OF TURBINE CHILLER AT #6 POWERHOUSE	.00		49000.00
10/23/02 510 480 VOLT BUS DUCT GROUNDED AT WEST SIDE OF HOSP 10/24/02 510 SWITCH CABINET FAULTED CAUSING POWER FAILURE IN	17856.44	.00	22769.00
	17132.97	.00	17132.97
10/30/02 510 6-POLE TXFMS DAMAGED BY ENTERGY EQUIPMT FAILURE	16902.00	.00	16902.00
11/12/02 510 C/W FLOW SWITCH FAILED CAUSING DAMAGE TO BOTH	15444.00	.00	15444.00
11/18/02 510 MAIN CHILLER STARTER FAILED AGAIN.	45696.39	.00	45696.39
12/06/02 510 UNDER GROUND FEEDER FAULT IN D SECTION 12/06/02 51F SWITCHGEAR AT CIRCUIT D FAILED	49000.00 38828.74		49000.00 P .00 S
12/27/02 510 SOUTH FEEDER SWITCH FAILED CAUSING CAMPUS-WIDE	87828.74	38828.74	49000.00 T
	10091.17	.00	10091.17

07-01-2003/12-13-2004 as of February 3, 2004

ACC.DATE COV	DESC OF LOSS - KEY 3	TOTAL-PAID CLM	.RECOV	NET-CLAIM	
08/12/03 510	BOTH COMPRESSORS ON YORK 80 TON CHILLER FAILED	12360.78	.00	12360.78	
08/19/03 510	NEBRASKA BOILDER #4 TUBES OVERFIRED.	.00	.00	25000.00	
08/19/03 510	15 TON CHILLER AT DOLAND ATHLETIC FIELD HOUSE	12674.35	.00	12675.00	
	POWER SURGE CAUSED PRIMARY WINDINGS ON TXFM	13808.30	.00	13808.30	
08/30/03 510	LAFAYETTE UTILITIES SYSTEMS CAUSED SINGLE PHASIN	600.36	.00	35000.00 P	
	POWER FAILURE CAUSED FOODS IN REFRIGERATOR TO	.00	.00	3655.00 S	
		600.36	.00	38655.00 T	
09/12/03 510	13800 Y CABLE FAILED NEAR BIOLOGY BLDG. SINGLE	.00	.00	49000.00	
	SINGLE PHASING CAUSED NUMEROUS MOTOR AND EQUIP	.00	.00	49000.00	
	AUTOMATIC SWITCH FOR GENERATOR FAULTED DURING	30939.56	.00	30939.56	
	TRANCE MODEL CGAFC50EAAA19R GROUNDED	.00	.00	40000.00	
	750 KVA TRANSFORMER FAULTED	.00	.00	35000.00	